

VEHICLE INSPECTION REPORT

WJ65YVK

Isuzu D-Max 2.5 TD

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT
V5 Buyer To Apply

Details

Reg. date	26/11/2015	VIN	MPATFS86JFT010740	CAP Below	£3,400.00
Year	2015	Body Style	Pickup Double Cab	Gearbox	MANUAL
Mileage	78,635 Miles Warranted	MOT Due	Expired	Gears	6
Fuel Type	Diesel	CAP Clean	£6,025.00	Axle Combi	4x4
Colour	WHITE	CAP Average	£4,850.00		

WARNING LIGHT ON DASH

Tyres

NSF

NSR

OSF


OSR

Spare

Features

- Park assist camera
- Digital radio
- Air conditioning
- Front electric windows
- Drivers airbag
- Passenger airbag
- Central locking
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Bumper Front
Scratched
Over 100mm Thru Paint

2: Bonnet
Chipped
Multiple Chips



3: Bumper Front
Scratched
Over 100mm Thru Paint

4: Wing nsf
Scratched
Over 25mm Thru Paint



5: Qtr Panel nsr
Scratched
Over 25mm Thru Paint

6: Qtr Panel osr
Scratched
Over 25mm Thru Paint



7: Qtr Panel osr
Chipped
Multiple Chips

8: Door osf
Dented
With Paint Damage



9: Wing osf
Dented
Over 30mm

10: Carpets Front
Soiled
Heavy



11: Fascia Panel
Broken
Replace

12: Seat Base Cover osf
Soiled
Heavy



13: Seat Base Cover nsf
Soiled
Heavy

14: Dash Warning Lights
Displayed
No Action

Interior

Carpet Condition	Poor	Upholstery Condition	Poor
Seat Condition	Poor	Odour	No
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	Fault